



# 5508 Bell Joint Leak Repair Clamps

## PRICE INFORMATION

**Use:** To repair leaking Ductile Iron, PVC C900 or Cast Iron Bell Joints

Nominal Pipe	WEIGHT		Working Range	LIST PRICE
	LBS.	KG		
4"	18	8	4.80" - 5.00"	\$ 898.23
6"	27	12	6.90" - 7.10"	\$ 974.68
8"	33	15	9.05" - 9.30"	\$ 1,352.12
10"	43	19	11.10" - 11.40"	\$ 1,772.57
12"	48	22	13.20" - 13.50"	\$ 2,097.46
14"	125	57	15.30"	POA
16"	150	68	17.40"	POA
18"	175	79	19.50"	POA
20"	200	91	21.60"	POA
24"	325	147	25.80"	POA



Body Casting: 4-12" - Ductile Iron per ASTM A536  
14-24" - Fabricated Steel

Gasket: NBR Nitrile Gasket

Coating: Epoxy coated

Bolts & Nuts: Low Alloy Steel per ASTM A325 and A563

### ROBAR INDUSTRIES LTD.

BC Phone (604) 591-8811 / 1-800-663-6553

Fax (604) 591-5288

Email: [waterworks@robarindustries.com](mailto:waterworks@robarindustries.com)

### LES PRODUITS INDUSTRIELS ROBAR INC.

QUEBEC

Phone (450) 441-7525 / 1-800-315-9525

Fax (450) 441-4894

Web: [www.Robarindustries.com](http://www.Robarindustries.com)